



Figure: 0043
Slight cracking in the roadway on Booran Road.




Figure: 0044
General view of the roadway on Booran Road.





Figure: 0045
Slight cracking in the roadway on Booran Road.



Figure: 0046
General view of the kerb and gutter on Booran Road.



Figure: 0047
General view of the crossover on Booran Road.



Figure: 0048
General view of the crossover on Booran Road.



Figure: 0049
General view of the substation and boundary fence on Booran Road.



Figure: 0050
General view of the boundary fence on Booran Road.



Figure: 0051
General view of the footpath on Booran Road.



Figure: 0052
General view of the footpath and fence on Booran Road.



Figure: 0053
General view of the footpath and fence on Booran Road.



Figure: 0054
General view of the traffic light on Booran Road.



Figure: 0055
Chipping in the kerb on Booran Road.



Figure: 0056
General view of the roadway on Booran Road.





Figure: 0057
Fine cracking in the roadway on Booran Road.



Figure: 0058
General view of the roadway on Booran Road.




Figure: 0059
General view of the kerb and gutter on Booran Road.





Figure: 0060
General view of the nature strip on Booran Road.