

Minor Defects		
Pg#	Description	Notes
21	Slight cracking in the tile floor in the entrance, outside the living room.	Refer to Figure 36 - No changes noted.
22	Slight cracking in the tile floor in the entrance, outside the living room.	Refer to Figure 37 - No changes noted.
22	Slight cracking in the tile floor in the entrance, outside the living room.	Refer to Figure 38 - No changes noted.
33	General view of the ceiling in the library.	Refer to Figure 72 - Showing hairline cracking at the southeast corner in the library.
34	Slight cracking the tile floor in the hallway, outside the library.	Refer to Figure 75 - No changes noted.
50	Fine cracking in tile floor in bedroom 1 en suite.	Refer to Figure 122 - No changes noted.
67	Bubbling paint in the right wall in the garage.	Refer to Figure 172 - No changes noted.
74	Fine cracking in the rear wall of the house.	Refer to Figure 194 - No changes noted.
75	Fine cracking in the rear wall of the house.	Refer to Figure 196 - No changes noted.
75	Fine cracking in the rear wall of the house.	Refer to Figure 197 - No changes noted.
77	Peeling in the rear wall of the house.	Refer to Figure 204 - Showing fine cracking in the rear wall of the house.
81	Fine cracking in the rear boundary wall, left side, outside the pool area.	Refer to Figure 214 - No changes noted.
81	Fine cracking in the rear boundary wall, left side, outside the pool area.	Refer to Figure 215 - No changes noted.
90	Fine cracking in the rear wall of the house, right side.	Refer to Figure 243 - No changes noted.
103	Seepage in rear wall in the storage hallway.	Refer to Figure 281 - No changes noted.
133	Fine cracking in the left wall, adjacent to the front entrance gate.	Refer to Figure 371 - No changes noted.
135	Chipping in the tile paving on the front side of the house, adjacent to front entrance stairway.	Refer to Figure 376 - No changes noted.
152	Fine cracking in the front boundary wall, adjacent to the entrance gate.	Refer to Figure 431 - No changes noted.
157	Fine cracking in the front wall of the house, left side.	Refer to Figure 445 - No changes noted.
159	Fine cracking in the front wall of the house.	Refer to Figure 450 - No changes noted.

***This assessment is included as part of a full coverage post-construction survey, unless otherwise stated.**