Defect ID	Route Name	Road Name	Suburb	Time Stamp	Type of Defect	Comments	Risk Classification
1	Adams Road from The Northern Road to Elizabeth Dr	Adams Road	LUDDENHAM	0:31	Spalling	NA	Minor
2	Adams Road from The Northern Road to Elizabeth Dr	Adams Road	LUDDENHAM	0:33	Spalling	NA	Minor
3	Adams Road from The Northern Road to Elizabeth Dr	Adams Road	LUDDENHAM	1:11	Spalling	NA	Minor
4	Adams Road from The Northern Road to Elizabeth Dr	Adams Road	LUDDENHAM	1:59	Cracking	Longitudinal Cracking	Minor
5	Adams Road from Elizabeth Dr to The Northern Road	Adams Road	LUDDENHAM	2:47	Cracking	Longitudinal Cracking	Minor
6	Adams Road from Elizabeth Dr to The Northern Road	Adams Road	LUDDENHAM	3:26	Spalling	NA	Minor
7	Adams Road from Elizabeth Dr to The Northern Road	Adams Road	LUDDENHAM	3:28	Pot Holing	NA	Minor